

Cleanup Site Details

Cleanup Site ID: 11638

Cleanup Site ID: 11638	Facility/Site ID: 20871	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Richland Uptown Shopping Center Parcel 26					Glossary
Alternate Names: Richland Uptown Shopping Center Parcel 26					
LOCATION					
Address: 1317 GEORGE WASHINGTON WAY		City: RICHLAND	Zip Code: 99354	County: Benton	
Latitude: 46.28717	Longitude: -119.27559	WRIA: 40	Legislative District: 8	Congressional District: 4	TRS: 9N 28E 2
DETAIL					
Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No			
Statute: MTCA	NFA Date: N/A	Current VCP? No		Past VCP? No	
Site Rank: N/A	NFA Reason: N/A	Brownfield? No			
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control?		No	
CLEANUP UNITS					
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Richland Uptown Shopping Center Parcel 26	Upland	Awaiting Cleanup	CE	Central Region	No Process
ACTIVE INSTITUTIONAL CONTROLS					
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County
There are no current Institutional Controls in effect for this site.					
AFFECTED MEDIA & CONTAMINANTS					
MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air
Petroleum-Other	C	C			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below					
SITE ACTIVITIES					
Activity	Status		Start Date	End Date/ Completion Date	
Early Notice Letter(s)	Completed			7/14/2017	