

Cleanup Site Details

Cleanup Site ID: 11642

Cleanup Site ID: 11642 Facility/Site ID: 4215 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Richland Uptown Shopping Center Parcel 14

Glossary

Alternate Names: Richland Uptown Shopping Center Parcel 14

LOCATION

Address: 1388 Jadwin Ave City: Richland Zip Code: 99354 County: Benton

Latitude: 46.28937 Longitude: -119.27623 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 9N 28E 2

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Richland Uptown Shopping Center Parcel 14	Upland	Awaiting Cleanup	CE	Central Region	No Process	

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA				
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		7/14/2017

Toxics Cleanup Program Report Generated: 7/24/2025 Page 1 of 1