

Cleanup Site Details

Cleanup Site ID: 11644

Cleanup Site ID: 11644	Facility/Site ID: 11498	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Richland Uptown Shopping Center Parcel 11					Glossary
Alternate Names: Richland Uptown Shopping Center Parcel 11					

LOCATION

Address: 1368 JADWIN AVE			City: RICHLAND	Zip Code: 99354	County: Benton
Latitude: 46.28845	Longitude: -119.27625	WRIA: 40	Legislative District: 8	Congressional District: 4	TRS: 9N 28E 2

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 1/23/2018	Current VCP? No Past VCP? Yes
Site Rank: N/A	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No
Site Manager: Winslow, Frank	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Richland Uptown Shopping Center Parcel 11	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup Program

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	B				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		7/14/2017
Non-LUST Ind Report Received	Completed		11/1/2017
VCP Receipt of Plan or Report	Completed		12/4/2017
VCP Opinion on Site Cleanup	Completed	12/7/2017	1/23/2018
Site Status Changed to NFA	Completed		1/23/2018