

Cleanup Site Details

Cleanup Site ID: 11644

Cleanup Site ID: 11644	Facility/Site ID: 11498	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Richland Uptown Shopping Center Parcel 11					Glossary
Alternate Names: Richland Uptown Shopping Center Parcel 11					
LOCATION					
Address: 1368 JADWIN AVE		City: RICHLAND	Zip Code: 99354	County: Benton	
Latitude: 46.28845	Longitude: -119.27625	WRIA: 40	Legislative District: 8	Congressional District: 4	TRS: 9N 28E 2
DETAIL					
Status: No Further Action	NFA Received? Yes	Is PSI site? No			
Statute: MTCA	NFA Date: 1/23/2018	Current VCP? No		Past VCP? Yes	
Site Rank: N/A	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No			
Site Manager: Winslow, Frank	Responsible Unit: Central	Active Institutional Control? No			
CLEANUP UNITS					
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Richland Uptown Shopping Center Parcel 11	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup Program
ACTIVE INSTITUTIONAL CONTROLS					
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County
There are no current Institutional Controls in effect for this site.					
AFFECTED MEDIA & CONTAMINANTS					
MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air
Petroleum-Other	RB	B			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below					
SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Early Notice Letter(s)	Completed		7/14/2017		
Non-LUST Ind Report Received	Completed		11/1/2017		
VCP Receipt of Plan or Report	Completed		12/4/2017		
VCP Opinion on Site Cleanup	Completed	12/7/2017	1/23/2018		
Site Status Changed to NFA	Completed		1/23/2018		