

Cleanup Site Details

Cleanup Site ID: 11645

Cleanup Site ID: 11645 Facility/Site ID: 10144 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Richland Uptown Shopping Center Parcel 10 [Glossary](#)

Alternate Names: Richland Uptown Shopping Center Parcel 10

LOCATION

Address: 1364 JADWIN AVE City: RICHLAND Zip Code: 99354 County: Benton
Latitude: 46.28831 Longitude: -119.27625 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 9N 28E 2

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Richland Uptown Shopping Center Parcel 10	Upland	Cleanup Started	CE	Central Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C	C				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		7/14/2017
VCP Receipt of Plan or Report	Completed		1/6/2021
VCP Receipt of Plan or Report	Completed		1/6/2021
VCP Opinion on Site Cleanup	Completed	1/7/2021	1/20/2021
VCP Status Request	Completed	6/6/2022	9/28/2022