

Cleanup Site Details

Cleanup Site ID: 11646

Cleanup Site ID: 11646	Facility/Site ID: 5431	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Richland Uptown Shopping Center Parcel 09					Glossary	
Alternate Names: Richland Uptown Shopping Center Parcel 09						
LOCATION						
Address: 1350 JADWIN AVE		City: RICHLAND	Zip Code: 99354	County: Benton		
Latitude: 46.28803	Longitude: -119.27625	WRIA: 40	Legislative District: 8	Congressional District: 4	TRS: 9N 28E 2	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 8/2/2017	Current VCP? No		Past VCP? No		
Site Rank: N/A	NFA Reason: Independent Cleanup Reviewed by Ecology	Brownfield? No				
Site Manager: Winslow, Frank	Responsible Unit: Central	Active Institutional Control? No				
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Richland Uptown Shopping Center Parcel 09	Upland	No Further Action Required	CE	Central Region	No Process	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	B					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Status Changed to NFA	Completed			8/2/2017		