

Cleanup Site Details

Cleanup Site ID: 11647

Cleanup Site ID: 11647 Facility/Site ID: 24112 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Richland Uptown Shopping Center Parcel 06 [Glossary](#)

Alternate Names: Richland Uptown Shopping Center Parcel 06

LOCATION

Address: 1340 JADWIN AVE City: RICHLAND Zip Code: 99354 County: Benton
Latitude: 46.28754 Longitude: -119.27581 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 9N 28E 2

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Richland Uptown Shopping Center Parcel 06	Upland	Awaiting Cleanup	CE	Central Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		7/14/2017