

Cleanup Site Details

Cleanup Site ID: 11724

Cleanup Site ID: 11724 Facility/Site ID: 27815219 UST ID: 100687 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: Mackners Transport

Alternate Names: Mackners Transport, MACKNERS TRANSPORT INC

LOCATION

Address: 400 E MOUNTAIN VIEW AVE City: ELLENSBURG Zip Code: 98926 County: Kittitas

Latitude: 46.98394 Longitude: -120.54311 WRIA: 39 Legislative District: 13 Congressional District: 8 TRS: 17N 18E 11

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 5/17/2022 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? Yes

Site Manager: Monahan, Mary Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Mackners Transport
 Upland
 No Further Action Required
 CE
 Monahan, Mary
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	_	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Lead	В							
Petroleum-Diesel	RB	RB						
Petroleum-Gasoline	RB							
Polycyclic Aromatic Hydrocarbons	В							

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above

S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		6/4/2011
LUST - Report Received	Completed		6/4/2011
Early Notice Letter(s)	Completed		3/30/2012
LUST - Report Received	Completed		5/23/2012
LUST - Report Received	Completed		8/16/2012
Early Notice Letter(s)	Completed		10/30/2013
VCP Receipt of Plan or Report	Completed		4/2/2015

Toxics Cleanup Program Report Generated: 11/14/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		9/30/2019			
LUST - Report Received	Completed		9/30/2019			
LUST - Report Received	Completed		9/30/2019			
LUST - Report Received	Completed		9/30/2019			
LUST - Report Received	Completed		9/30/2019			
VCP Opinion on Site Cleanup	Completed	12/15/2021	5/17/2022			
Petroleum Impacts to Groundwater Model Remedies	Completed		5/17/2022			
Site Status Changed to NFA	Completed		5/17/2022			

Cleanup Site ID: 11724