

Cleanup Site Details

Cleanup Site ID: 11724

Cleanup Site ID: 11724
Facility/Site ID: 27815219
UST ID: 100687
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Mackners Transport
[Glossary](#)
Alternate Names: Mackners Transport, MACKNERS TRANSPORT INC

LOCATION

Address: 400 E MOUNTAIN VIEW AVE
City: ELLENSBURG
Zip Code: 98926
County: Kittitas
Latitude: 46.98394
Longitude: -120.54311
WRIA: 39
Legislative District: 13
Congressional District: 8
TRS: 17N 18E 11

DETAIL

Status: No Further Action
NFA Received? Yes
Is PSI site? No
Statute: MTCA
NFA Date: 5/17/2022
Current VCP? No
Past VCP? Yes
Site Rank: N/A
NFA Reason: Voluntary Cleanup Program Review
Brownfield? Yes
Site Manager: Monahan, Mary
Responsible Unit: Central
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Mackners Transport	Upland	No Further Action Required	CE	Monahan, Mary	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	B					
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB					
Polycyclic Aromatic Hydrocarbons	B					

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		6/4/2011
LUST - Report Received	Completed		6/4/2011
Early Notice Letter(s)	Completed		3/30/2012
LUST - Report Received	Completed		5/23/2012
LUST - Report Received	Completed		8/16/2012
Early Notice Letter(s)	Completed		10/30/2013
VCP Receipt of Plan or Report	Completed		4/2/2015

Cleanup Site Details

Cleanup Site ID: 11724

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		9/30/2019
LUST - Report Received	Completed		9/30/2019
LUST - Report Received	Completed		9/30/2019
LUST - Report Received	Completed		9/30/2019
LUST - Report Received	Completed		9/30/2019
VCP Opinion on Site Cleanup	Completed	12/15/2021	5/17/2022
Petroleum Impacts to Groundwater Model Remedies	Completed		5/17/2022
Site Status Changed to NFA	Completed		5/17/2022