

Cleanup Site Details

Cleanup Site ID: 11805

Cleanup Site ID: 11805 Facility/Site ID: 1804 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Kenneth Sasse Property [Glossary](#)

Alternate Names: Kenneth Sasse Property

LOCATION

Address: 277A Haygood Cutoff Rd City: Tonasket Zip Code: 98855 County: Okanogan
Latitude: 48.62390 Longitude: -119.59201 WRIA: 49 Legislative District: 7 Congressional District: 4 TRS: 36N 26E 17

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 1/31/2024 Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: Independent Cleanup Reviewed by Ecology Brownfield? No
Site Manager: Winslow, Frank Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Kenneth Sasse Property	Upland	No Further Action Required	CE	Central Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					
Petroleum-Other	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		3/8/2012
Early Notice Letter(s)	Completed		3/29/2012
Site Hazard Assessment/Federal Site Inspection	Completed	5/10/2012	8/31/2012
Hazardous Sites Listing/NPL	Completed		9/11/2012
Remove site from Hazardous Sites List	Completed		1/31/2024
Site Status Changed to NFA	Completed		1/31/2024