

## Cleanup Site Details

Cleanup Site ID: 11853

Cleanup Site ID: 11853 Facility/Site ID: 21786898 UST ID: 5617 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: Cascade Laundry

Alternate Names: Cascade Laundry, CASCADE LAUNDRY CORP

LOCATION

Address: 205 PROSPECT ST City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.75308 Longitude: -122.48169 WRIA: 1 Legislative District: 42 Congressional District: 2 TRS: 38N 3E 30

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Vik, Kim Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cascade Laundry	Upland	Cleanup Started	NW	Vik, Kim	Standard Voluntary Cleanup

#### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
	Media	The state of the s		Number	County	

There are no current Institutional Controls in effect for this site.

### **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С			С	
Halogenated Solvents	С	С			С	
Other Non-Halogenated Organics	С	С				
Petroleum-Diesel	С					
Petroleum-Gasoline	С	С				
Petroleum-Other	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated RB - Remediated-Below

#### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/10/2010
Initial Investigation / Federal Preliminary Assessment	Completed		5/10/2011
Early Notice Letter(s)	Completed		5/8/2012
Early Notice Letter(s)	Completed		7/18/2012
VCP Receipt of Plan or Report	Completed		6/24/2016

Toxics Cleanup Program Report Generated: 11/18/2025 Page 1 of 2



# Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
VCP Receipt of Plan or Report	Completed		6/24/2016			
VCP Opinion on Remedial Investigation Work Plan	Completed	6/24/2016	10/30/2017			
LUST - Notification	Completed		11/8/2017			
VCP Receipt of Plan or Report	Completed		5/16/2018			
VCP Status Request	Completed	1/20/2021	2/26/2021			
LUST - Report Received	Completed		3/10/2021			
LUST - Report Received	Completed		3/10/2021			
VCP Opinion on Remedial Investigation	Completed	3/10/2021	6/24/2021			
VCP Status Request	Completed		5/24/2023			
VCP Technical Assistance	Completed		9/4/2024			
SHARP Assessment	Completed		9/5/2024			
VCP Receipt of Plan or Report	Completed		11/4/2024			

Cleanup Site ID: 11853