

# Cleanup Site Details

Cleanup Site ID: 11853

Cleanup Site ID: 11853      Facility/Site ID: 21786898      UST ID: 5617      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Cascade Laundry      [Glossary](#)

Alternate Names: Cascade Laundry, CASCADE LAUNDRY CORP

## LOCATION

Address: 205 PROSPECT ST      City: BELLINGHAM      Zip Code: 98225      County: Whatcom  
Latitude: 48.75308      Longitude: -122.48169      WRIA: 1      Legislative District: 42      Congressional District: 2      TRS: 38N 3E 30

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? Yes  
Statute: MTCA      NFA Date: N/A      Current VCP? Yes      Past VCP? Yes  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Vik, Kim      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cascade Laundry	Upland	Cleanup Started	NW	Vik, Kim	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C			C	
Halogenated Solvents	C	C			C	
Other Non-Halogenated Organics	C	C				
Petroleum-Diesel	C					
Petroleum-Gasoline	C	C				
Petroleum-Other	C					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/10/2010
Initial Investigation / Federal Preliminary Assessment	Completed		5/10/2011
Early Notice Letter(s)	Completed		5/8/2012
Early Notice Letter(s)	Completed		7/18/2012
VCP Receipt of Plan or Report	Completed		6/24/2016

# Cleanup Site Details

Cleanup Site ID: 11853

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		6/24/2016
VCP Opinion on Remedial Investigation Work Plan	Completed	6/24/2016	10/30/2017
LUST - Notification	Completed		11/8/2017
VCP Receipt of Plan or Report	Completed		5/16/2018
VCP Status Request	Completed	1/20/2021	2/26/2021
LUST - Report Received	Completed		3/10/2021
LUST - Report Received	Completed		3/10/2021
VCP Opinion on Remedial Investigation	Completed	3/10/2021	6/24/2021
VCP Status Request	Completed		5/24/2023
VCP Technical Assistance	Completed		9/4/2024
SHARP Assessment	Completed		9/5/2024
VCP Receipt of Plan or Report	Completed		11/4/2024