

Cleanup Site Details

Cleanup Site ID: 11853

Cleanup Site ID: 11853 Facility/Site ID: 21786898 UST ID: 5617 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: Cascade Laundry

Alternate Names: Cascade Laundry, CASCADE LAUNDRY CORP

LOCATION

Address: 205 PROSPECT ST City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.75308 Longitude: -122.48169 WRIA: 1 Legislative District: 42 Congressional District: 2 TRS: 38N 3E 30

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Vik, Kim Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Cascade Laundry
 Upland
 Cleanup Started
 NW
 Vik, Kim
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Benzene	С	С			С			
Halogenated Solvents	С	С			С			
Other Non-Halogenated Organics	С	С						
Petroleum-Diesel	С							
Petroleum-Gasoline	С	С						
Petroleum-Other	С							

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/10/2010
Initial Investigation / Federal Preliminary Assessment	Completed		5/10/2011
Early Notice Letter(s)	Completed		5/8/2012
Early Notice Letter(s)	Completed		7/18/2012
VCP Receipt of Plan or Report	Completed		6/24/2016

Toxics Cleanup Program Report Generated: 1/17/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
VCP Receipt of Plan or Report	Completed		6/24/2016			
VCP Opinion on Remedial Investigation Work Plan	Completed	6/24/2016	10/30/2017			
LUST - Notification	Completed		11/8/2017			
VCP Receipt of Plan or Report	Completed		5/16/2018			
VCP Status Request	Completed	1/20/2021	2/26/2021			
LUST - Report Received	Completed		3/10/2021			
LUST - Report Received	Completed		3/10/2021			
VCP Opinion on Remedial Investigation	Completed	3/10/2021	6/24/2021			
VCP Status Request	Completed		5/24/2023			
VCP Technical Assistance	Completed		9/4/2024			
Site Hazard Assessment/Federal Site Inspection	Completed		9/5/2024			
VCP Receipt of Plan or Report	Completed		11/4/2024			

Cleanup Site ID: 11853