

Cleanup Site Details

Cleanup Site ID: 11868

Cleanup Site ID: 11868	Facility/Site ID: 19519	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Sixth & Lenora Apartments					Glossary
Alternate Names: Sixth & Lenora Apartments					

LOCATION

Address: 2121 6TH AVE			City: SEATTLE	Zip Code: 98121	County: King
Latitude: 47.61531	Longitude: -122.34045	WRIA: 8	Legislative District: 36	Congressional District: 7	TRS: 25N 4E 31

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? Yes
Statute: MTCA	NFA Date: 6/4/2012	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Initial Investigation	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Sixth & Lenora Apartments	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		11/8/2011
Non-LUST Ind Report Received	Completed		11/8/2011
Initial Investigation / Federal Preliminary Assessment	Completed		1/9/2012
Site Status Changed to NFA	Completed		6/4/2012