DEPARTMENT OF ECOLOG State of Washingt			Cleanup Site Details						Cleanup Site ID: 119		
Cleanup Site ID: 119 Facility/Site ID:			03 <b>UST ID:</b> N/A			5	Site Page	Site Doc	uments	<u>View Map</u>	
Cleanup Site Name	: BASIN RECYCL	ING & RELO	DAD							<u>Glossary</u>	
Alternate Names: BASIN RECYCLING & RELOAD											
LOCATION											
Address: 27TH & E	ELY		City: KENNEWICK				Zip Code: 99336 County: Benton				
Latitude: 46.18406 Longitude: -119.15902			WRIA: 31	31 Legislative District: 8			Congressional District: 4 TRS: 8N 29E 11				
DETAIL											
Status: No Further Action NFA			Received?	Yes Is P				site?	No		
Statute: MTCA	MTCA NFA			8/18/1992 Current				nt VCP?	No Pas	t VCP? No	
Site Rank: N/A NFA			Reason:	n: SHA, IRAP, or VCP			Brownfield? No				
Site Manager: Central Region Res			onsible Unit:	: Central A			Active	e Institutio	nal Contro	I? No	
CLEANUP UNITS											
Cleanup Unit Name Unit Typ		Unit Type	Unit Status		Resp Unit	Unit M	Unit Manager		Current Process		
BASIN RECYCLING & RELOAD		Upland	No Further Action Required		CE	Centra	Central Region		No Process		
ACTIVE INSTITUTIO	ONAL CONTROLS										
Instrument Type Restriction Re Media Re		Restr	trictions/Requirements			Date Recordir Numbe		g Recording County		Tax Parcel	
There are no current Institutional Controls in effect for this site.											
AFFECTED MEDIA & CONTAMINANTS											
						MEDIA					
Contaminant			So	I Groundwater		Surface	ce Water Sediment		Air	Bedrock	
Metals Priority Pollutants			S								
Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below											
SITE ACTIVITIES											
Activity						Status		Start Date	rt Date End Date/ Completion Dat		
Site Discovery/Release Report Received					C	Completed			3/1/1988		
Site Status Changed to NFA						Completed 8/18/1992				8/18/1992	