

Cleanup Site Details

Cleanup Site ID: 120

Cleanup Site ID: 120	Facility/Site ID: 305	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: EASTGATE PARK					
Alternate Names: EASTGATE PARK					
LOCATION					
Address: E 10TH AVE & OAK ST		City: KENNEWICK	Zip Code: 99336	County: Benton	
Latitude: 46.19783	Longitude: -119.09673	WRIA: 31	Legislative District: 8	Congressional District: 4	TRS: 8N 30E 7
DETAIL					
Status: No Further Action	NFA Received? Yes	Is PSI site? No			
Statute: MTCA	NFA Date: 1/27/2003	Current VCP? No		Past VCP? No	
Site Rank: N/A	NFA Reason: Site Hazard Assessment	Brownfield? No			
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control?		No	
CLEANUP UNITS					
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
EASTGATE PARK	Upland	No Further Action Required	CE	Central Region	No Process
ACTIVE INSTITUTIONAL CONTROLS					
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County
There are no current Institutional Controls in effect for this site.					
AFFECTED MEDIA & CONTAMINANTS					
MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air
Pesticides-Unspecified	B	S	S		
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below					
SITE ACTIVITIES					
Activity	Status		Start Date	End Date/ Completion Date	
Site Discovery/Release Report Received	Completed			3/1/1988	
Site Hazard Assessment/Federal Site Inspection	Completed		9/25/2002	1/27/2003	
Site Status Changed to NFA	Completed			1/27/2003	