

Г

Cleanup Site Details

Cleanup Site ID: 12095

	12095 Fa	cility/Site ID: 4	450	UST ID: 7829	9	<u>Site Pa</u>	ige S	Site Docun	<u>nents</u>	<u>View Map</u>	
Cleanup Site Nam	e: Boise Cascad	e Mill								<u>Glossary</u>	
Alternate Names: CASCADE PLYWC ENTERPRISES LL	OD LOG YARD,	Boise Cascade	Yakima, BOISE	E CASCADE YA	KIMA CO	OMPLEX, Boise	Cascad	e Yakima I			
LOCATION											
Address: 805 N 7	TH ST			City: YAKIMA		Zip Code: 9	8901	Count	y: Yakir	na	
Latitude: 46.61472	2 Longitude:	-120.49905	WRIA: 37	Legislative Dis	strict: 1	15 Congres	sional I	District: 4	TRS	: 13N 19E 18	
DETAIL											
Status: Cleanup	Started	NFA	Received?	No		ls	s PSI sit	e? N	0		
Statute: MTCA		NFA	Date:	N/A		с	Current VCP? No Past VCP? No				
Site Rank: N/A NFA Reason:				N/A		В	rownfie	eld? Ye	es		
Site Manager: Zin	za, John	Resp	onsible Unit:	Central		А	ctive In	stitutiona	I Contro	No No	
CLEANUP UNITS											
Cleanup l	Jnit Name	Unit Type	Unit S	Status	Resp Unit	Unit Manag	er	Cı	Current Process		
Boise Cascade Mill		Upland	Cleanup	o Started	CE	Zinza, Johr	n l	Ecology-s	upervise	d or conducted	
ACTIVE INSTITUTI	ONAL CONTRO	LS									
Instrument Type	Restriction Media	Rest	rictions/Requir	rements	D		ording mber	Recor Cou		Tax Parcel	
There are no currer	it Institutional Cor	ntrols in effect fo	or this site.								
AFFECTED MEDIA	& CONTAMINA	NTS									
AFFECTED MEDIA	& CONTAMINA	NTS				MEI	DIA				
AFFECTED MEDIA	& CONTAMINA	NTS	Soi		vater	MEI Surface Water		iment	Air	Bedrock	
	& CONTAMINA	NTS	Soi C	il Groundv C	vater			iment	Air	Bedrock	
Contaminant	& CONTAMINA	NTS			vater	Surface Water		iment	Air	Bedrock	
Contaminant Arsenic		NTS	С		vater	Surface Water		iment	Air	Bedrock	
Contaminant Arsenic Benzene		NTS	С	C	vater	Surface Water		iment	Air	Bedrock	
Contaminant Arsenic Benzene Halogenated Solver		NTS	C C	C	vater	Surface Water C		iment	Air	Bedrock	
Contaminant Arsenic Benzene Halogenated Solver Lead	nts	NTS	с С С	C C	vater	Surface Water C C		iment /	Air	Bedrock	
Contaminant Arsenic Benzene Halogenated Solver Lead Metals - Other	nts	NTS	C C C C C	C C	vater	Surface Water C C C C		iment /	Air	Bedrock	
Contaminant Arsenic Benzene Halogenated Solver Lead Metals - Other Other Non-Halogen	nts ated Organics	NTS	C C C C C C	C C	vater	Surface Water C C C C C		iment	Air	Bedrock	
Contaminant Arsenic Benzene Halogenated Solver Lead Metals - Other Other Non-Halogen Petroleum-Diesel	nts ated Organics	NTS	C C C C C C C	C C	vater	Surface Water C C C C C		iment in a state in a	Air	Bedrock	
Contaminant Arsenic Benzene Halogenated Solver Lead Metals - Other Other Non-Halogen Petroleum-Diesel Petroleum-Gasoline	nts ated Organics	NTS	C C C C C C C C C	C C	vater	Surface Water C C C C C		iment /	Air	Bedrock Bedrock	
Contaminant Arsenic Benzene Halogenated Solver Lead Metals - Other Other Non-Halogen Petroleum-Diesel Petroleum-Gasoline Petroleum-Other	ated Organics	NTS	C C C C C C C C C C C C	C C	vater	Surface Water C C C C C		iment i	Air	Bedrock Bedrock	



Cleanup Site Details

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date					
Site Discovery/Release Report Received	Completed		12/1/2008					
Non-LUST Ind Report Received	Completed		6/26/2014					
Early Notice Letter(s)	Completed		3/4/2016					
Order/Decree/Amendment	In Process	6/3/2016						
Remedial Investigation and/or FS Work Plan	Completed	2/17/2017	1/29/2019					
Remedial Investigation and/or Feasibility Study	In Process	1/29/2019						
Interim Action - Plan	Canceled		5/4/2023					
Remedial Investigation and/or Feasibility Study	Planned	8/1/2023	12/31/2023					