

Cleanup Site Details

Cleanup Site ID: 12095

Cleanup Site ID: 12095 Facility/Site ID: 450 UST ID: 7829 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Boise Cascade Mill

[Glossary](#)

Alternate Names: BOISE CASCADE COMPLEX YAKIMA, BOISE CASCADE CORP, Boise Cascade Corp Yakima, Boise Cascade Mill, BOISE CASCADE PLYWOOD LOG YARD, Boise Cascade Yakima, BOISE CASCADE YAKIMA COMPLEX, Boise Cascade Yakima LUST, DUNOLLIE ENTERPRISES LLC YAKIMA, Old Yakima Landfill, Yakima Landfill, YAKIMA RESOURCES, YAKIMA RESOURCES LLC

LOCATION

Address: 805 N 7TH ST **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.61472 **Longitude:** -120.49905 **WRIA:** 37 **Legislative District:** 15 **Congressional District:** 4 **TRS:** 13N 19E 18

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** Yes
Site Manager: Zinza, John **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boise Cascade Mill	Upland	Cleanup Started	CE	Zinza, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C	C			
Benzene	C					
Halogenated Solvents		C				
Lead	C		C			
Metals - Other	C	C	C			
Other Non-Halogenated Organics	C		C			
Petroleum-Diesel	C	C	C			
Petroleum-Gasoline	C					
Petroleum-Other	C					
Polychlorinated biPhenyls (PCB)	S					
Polycyclic Aromatic Hydrocarbons	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 12095

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		12/1/2008
Non-LUST Ind Report Received	Completed		6/26/2014
Early Notice Letter(s)	Completed		3/4/2016
Order/Decree/Amendment	In Process	6/3/2016	
Remedial Investigation and/or FS Work Plan	Completed	2/17/2017	1/29/2019
Remedial Investigation and/or Feasibility Study	In Process	1/29/2019	
Interim Action - Plan	Canceled		5/4/2023
Remedial Investigation and/or Feasibility Study	Planned	8/1/2023	12/31/2023