

Cleanup Site ID: 12095

Cleanup Site Details

Facility/Site ID: 450 **UST ID:** 7829 Site Page **Site Documents** View Map

Cleanup Site ID: 12095

Cleanup Site Name: Boise Cascade Mill **Glossary**

Alternate Names: BOISE CASCADE COMPLEX YAKIMA, BOISE CASCADE CORP, Boise Cascade Corp Yakima, Boise Cascade Mill, BOISE CASCADE PLYWOOD LOG YARD, Boise Cascade Yakima, BOISE CASCADE YAKIMA COMPLEX, Boise Cascade Yakima LUST, DUNOLLIE

ENTERPRISES LLC YAKIMA, Old Yakima Landfill, Yakima Landfill, YAKIMA RESOURCES, YAKIMA RESOURCES LLC

LOCATION

Address: 805 N 7TH ST City: YAKIMA **Zip Code:** 98901 County: Yakima

Congressional District: 4 Latitude: 46.61472 Longitude: -120.49905 **WRIA:** 37 Legislative District: 15 TRS: 13N 19E 18

DETAIL

Status: Cleanup Started NFA Received? Νo Is PSI site? No

Current VCP? Past VCP? No NFA Date: Statute: MTCA N/A No

NFA Reason: Site Rank: N/A Brownfield? N/A Yes

Site Manager: Zinza, John Responsible Unit: Central **Active Institutional Control?** Nο

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boise Cascade Mill	Upland	Cleanup Started	CE	Zinza, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Lyne Restrictions/Requirements Date	ording Tax Parcel	
--	-------------------	--

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic	С	С	С				
Benzene	С						
Halogenated Solvents		С					
Lead	С		С				
Metals - Other	С	С	С				
Other Non-Halogenated Organics	С		С				
Petroleum-Diesel	С	С	С				
Petroleum-Gasoline	С						
Petroleum-Other	С						
Polychlorinated biPhenyls (PCB)	S						
Polycyclic Aromatic Hydrocarbons	С						

Key:

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected

R - Remediated

RB - Remediated-Below

Toxics Cleanup Program Report Generated: 11/11/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed		12/1/2008		
Non-LUST Ind Report Received	Completed		6/26/2014		
Early Notice Letter(s)	Completed		3/4/2016		
Order/Decree/Amendment	In Process	6/3/2016			
Remedial Investigation and/or FS Work Plan	Completed	2/17/2017	1/29/2019		
Remedial Investigation and/or Feasibility Study	In Process	1/29/2019			
Interim Action - Plan	Canceled		5/4/2023		
Remedial Investigation and/or Feasibility Study	Planned	8/1/2023	12/31/2023		

Cleanup Site ID: 12095