

Cleanup Site Details

Cleanup Site ID: 12115

Cleanup Site ID: 12115 **Facility/Site ID:** 9809 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Whitehead Tyee [Glossary](#)
Alternate Names: Seattle Iron & Metals Corp Truck Parking, Whitehead Tyee, Whitehead Tyee Property

LOCATION

Address: 730 S Myrtle St **City:** Seattle **Zip Code:** 98108 **County:** King
Latitude: 47.53984 **Longitude:** -122.32542 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 29

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Butler, David **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------|-----------|-----------------|-----------|---------------|---------------------------------|
| Whitehead Tyee | Upland | Cleanup Started | NW | Butler, David | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|--|-------------------|---------------------------|------|------------------|------------------|------------|
| There are no current Institutional Controls in effect for this site. | | | | | | |

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|---------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Dioxins/Furans | C | C | | | | |
| Halogenated Solvents | C | C | | | | |
| Non-Halogenated Solvents | C | | | | | |
| Other Halogenated Organics | C | C | | | | |
| Petroleum-Diesel | | C | | | | |
| Petroleum-Gasoline | | C | | | | |
| Petroleum-Other | C | C | | | | |
| Polychlorinated biPhenyls (PCB) | C | S | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed | | 4/1/2000 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 4/23/2013 |
| Early Notice Letter(s) | Completed | | 4/24/2013 |

Cleanup Site Details

Cleanup Site ID: 12115

| SITE ACTIVITIES | | | |
|---|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| VCP Receipt of Plan or Report | Completed | | 10/22/2013 |
| VCP Opinion on Remedial Investigation Work Plan | Completed | 10/22/2013 | 3/6/2014 |
| VCP Receipt of Plan or Report | Completed | | 1/2/2014 |
| VCP Opinion on Remedial Investigation Work Plan | Canceled | 1/2/2014 | |
| VCP Receipt of Plan or Report | Completed | | 5/22/2014 |
| VCP Opinion on Remedial Investigation | Canceled | 5/22/2014 | |
| Order/Decree/Amendment | In Process | 6/1/2015 | |
| Site Hazard Assessment/Federal Site Inspection | Completed | 1/8/2016 | 6/8/2016 |
| Hazardous Sites Listing/NPL | Completed | | 6/8/2016 |
| Interim Action - Plan | Completed | 8/1/2016 | 5/1/2017 |
| Interim Action - Construction | In Process | 8/25/2017 | |
| Remedial Investigation and/or FS Work Plan | In Process | 2/1/2018 | |