

Cleanup Site Details

Cleanup Site ID: 12208

Cleanup Site ID: 12208 Facility/Site ID: 11376787 UST ID: 6086 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Burien Chevrolet [Glossary](#)

Alternate Names: Burien Chevrolet, GLEN GRANT CHEV, Glen Grant Chevrolet, Glen Grant Chevrolet Inc

LOCATION

Address: 14400 1ST AVE S City: BURIEN Zip Code: 98168 County: King
Latitude: 47.47369 Longitude: -122.33410 WRIA: 9 Legislative District: 34 Congressional District: 7 TRS: 23N 4E 19

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Burien Chevrolet	Upland	Awaiting Cleanup	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/9/2013
Site Discovery/Release Report Received	Completed		4/9/2013
LUST - Report Received	Completed		4/16/2013
Initial Investigation / Federal Preliminary Assessment	Completed		4/18/2013
Early Notice Letter(s)	Completed		10/4/2013
LUST - Report Received	Completed		10/22/2014