

# Cleanup Site Details

Cleanup Site ID: 1229

Cleanup Site ID: 1229      Facility/Site ID: 2177      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Port of Seattle N Terminal 115      [Glossary](#)

**Alternate Names:** M & T CHEMICALS INC, MRI, PORT OF SEATTLE N TERMINAL 115, PORT OF SEATTLE TERMINAL 115, PROELER, Proler Recycling Inc Seattle, SCHNITZER STEEL INC, SEATTLE PORT OF N TERMINAL 115

## LOCATION

**Address:** 6000 W MARGINAL WAY      **City:** SEATTLE      **Zip Code:** 98106      **County:** King  
**Latitude:** 47.54804      **Longitude:** -122.34365      **WRIA:** 9      **Legislative District:** 34      **Congressional District:** 7      **TRS:** 24N 4E 19

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 5 - Lowest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Nale, Cliff      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port of Seattle N Terminal 115	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Dioxins/Furans	S					
Metals Priority Pollutants	C	C				
Other Non-Halogenated Organics	C	C				
Petroleum-Diesel		C				
Petroleum-Gasoline	S	C				
Petroleum-Other		C				
Polychlorinated biPhenyls (PCB)	C					
Polycyclic Aromatic Hydrocarbons	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	8/21/1997	1/7/1998

# Cleanup Site Details

Cleanup Site ID: 1229

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Hazardous Sites Listing/NPL	Completed		2/17/1998
Order/Decree/Amendment	In Process	1/1/2010	
Remedial Investigation and/or FS Work Plan	Completed	3/2/2011	5/9/2013
Remedial Investigation and/or Feasibility Study	In Process	2/28/2015	
Site Hazard Assessment/Federal Site Inspection	Completed		3/21/2024