

Cleanup Site Details

Cleanup Site ID: 1229

Cleanup Site ID: 1229 Facility/Site ID: 2177 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Port of Seattle N Terminal 115 [Glossary](#)

Alternate Names: M & T CHEMICALS INC, MRI, PORT OF SEATTLE N TERMINAL 115, PORT OF SEATTLE TERMINAL 115, PROELER, Proler Recycling Inc Seattle, SCHNITZER STEEL INC, SEATTLE PORT OF N TERMINAL 115

LOCATION

Address: 6000 W MARGINAL WAY **City:** SEATTLE **Zip Code:** 98106 **County:** King
Latitude: 47.54804 **Longitude:** -122.34365 **WRIA:** 9 **Legislative District:** 34 **Congressional District:** 7 **TRS:** 24N 4E 19

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Sanchez, Maureen **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port of Seattle N Terminal 115	Upland	Cleanup Started	NW	Sanchez, Maureen	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Dioxins/Furans	S					
Metals Priority Pollutants	C	C				
Other Non-Halogenated Organics	C	C				
Petroleum-Diesel		C				
Petroleum-Gasoline	S	C				
Petroleum-Other		C				
Polychlorinated biPhenyls (PCB)	C					
Polycyclic Aromatic Hydrocarbons	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	8/21/1997	1/7/1998

Cleanup Site Details

Cleanup Site ID: 1229

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		2/17/1998
Order/Decree/Amendment	In Process	1/1/2010	
Remedial Investigation and/or FS Work Plan	Completed	3/2/2011	5/9/2013
Remedial Investigation and/or Feasibility Study	In Process	2/28/2015	