ECOLOGY State of Washington		Cleanup	Site D	eta	ils			Cleanup S	Site ID: 12300		
Cleanup Site ID: 12300 Faci	l6139 l	UST ID: 620356 <u>Sit</u>			Site Page	age <u>Site Documents</u> <u>View Map</u>					
Cleanup Site Name: Independent Me	etals Plant 2								<u>Glossary</u>		
Alternate Names: Independent Metal	ls 2, Independ	lent Metals Plant 2,	Independent M	/letals \$	S Kenyo	n St, Silver	Bay Lo	gging			
LOCATION											
Address: 816 S KENYON ST & 7814	8TH AVE S	Ci	ty: SEATTLE		Zip C	ode: 9810)8	County: Kin	g		
Latitude: 47.53240 Longitude: -	WRIA: 9 Le	gislative Dist	rict: 1	1 C	ongressio	nal Dist	rict: 9 TF	RS: 24N 4E 29			
DETAIL											
Status: Cleanup Started	Received? No				ls PS	SI site?	No				
Statute: MTCA	te: MTCA NFA Date:					Curr	ent VC	ent VCP? No Past VCP? No			
Site Rank: 4 - Low-Moderate Risk	NFA	Reason: N//	٩			Brov	vnfield?	No			
Site Manager: Schwarz, Julia	Resp	onsible Unit: No	rthwest			Activ	ve Instit	utional Cont	rol? No		
CLEANUP UNITS											
Cleanup Unit Name Unit 1		it Type Unit Status		Resp Unit Un		nit Manager		Current	Process		
Independent Metals 2	Upland	Cleanup Sta		NW	Schwarz, Julia		Ecology-supervised		sed or conducted		
ACTIVE INSTITUTIONAL CONTROLS	S										
Instrument Type Restriction Media	Rest	rictions/Requireme	irements		Date Recordi				Tax Parcel		
AFFECTED MEDIA & CONTAMINAN	TS					MEDIA					
	TS	Soil	Groundwa	ater	Surface	MEDIA Water		nt Air	Bedrock		
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic	TS	Soil C	Groundwa	ater	Surface		Sedime	nt Air	Bedrock		
Contaminant	TS			ater	Surface			nt Air	Bedrock		
Contaminant Arsenic	TS	C	С	ater	Surface			nt Air	Bedrock		
Contaminant Arsenic Benzene	TS	C S	C	ater				int Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans	TS	C S S	C	ater				Int Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides	TS	C S S S	C S S	ater				nt Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents	TS	C S S S C	C S S C	ater	S	Water		int Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead	TS	C S S S C C	C S S C C C	ater	S	Water		ent Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury	TS	C S S S C C C S	C S S C C C S	ater	S C C	Water		Int Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury Metals - Other	TS	C S S S C C C S	C S S C C C C S S S	ater	S C C	Water		Int Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury Metals - Other Non-Halogenated Pesticides	TS	C S S S C C C S S S	C S S C C C C S S S S	ater	S C C	Water		int Air Air	Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury Metals - Other Non-Halogenated Pesticides Organotins	TS	C S S C C C C S S S S	C S S C C C C S S S S S S	ater	C C C	Water		ent Air int	Bedrock Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury Metals - Other Non-Halogenated Pesticides Organotins Other Non-Halogenated Organics	TS	C S S C C C C S S S S S S	C S S C C C C C S S S S S S S S	ater	C C C S	Water		int Air int	Bedrock Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury Metals - Other Non-Halogenated Pesticides Organotins Other Non-Halogenated Organics	TS	C S S C C C C S S S S S S S C	C S S C C C C C S S S S S S S S C	ater	C C C S	Water		int Air int Air int Internet	Bedrock Bedrock		
Contaminant Arsenic Benzene Dioxins/Furans Halogenated Pesticides Halogenated Solvents Lead Mercury Metals - Other Non-Halogenated Pesticides Organotins Other Non-Halogenated Organics Petroleum-Diesel Petroleum-Gasoline	TS	C S S C C C C S S S S S S C S	C S S C C C C S S S S S S S S S S S S S	ater	S C C C S S S	Water		Image: Second	Bedrock		



Cleanup Site Details

Cleanup Site ID: 12300

Contaminant Polychlorinated biPhenyls (PCB)		Soil Groundwate		Surface Water	Sediment	Air	Bedrock	
		S	S	С				
Polycyclic Aromatic Hydrocarbons		S	S	S				
Key: B - Below Cleanup Level S - Suspected	C - Confirmed Above Cl R - Remediated	eanup Level	RA - Remediated RB - Remediated				1	
SITE ACTIVITIES								
Activity				Status	Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received				Completed		1/1/2009		
Initial Investigation / Federal Preliminary Assessment				Completed		2/14/2014		
Early Notice Letter(s)				Completed		2/24/2014		
Early Notice Letter(s)	(Completed		3/11/2014				
Site Hazard Assessment	(Completed	12/15/2014	5/2014 10/27/201				
Hazardous Sites Listing				Completed		10)/30/2015	
LUST - Notification				Completed		8/10/2017		
LUST - Report Received				Completed		8/10/2017		
Order/Decree/Amendment				In Process 5/19/2022				
Remedial Investigation and/or FS Work Plan				Completed 11/30/202		5/11/2023		
Remedial Investigation and/o	1	In Process 5/11/20		11/2023				
SHARP Assessment				Completed		8/14/2024		