

# Cleanup Site Details

Cleanup Site ID: 12300

Cleanup Site ID: 12300      Facility/Site ID: 16139      UST ID: 620356      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Independent Metals Plant 2      [Glossary](#)

Alternate Names: Independent Metals 2, Independent Metals Plant 2, Independent Metals S Kenyon St, Silver Bay Logging

## LOCATION

Address: 816 S KENYON ST & 7814 8TH AVE S      City: SEATTLE      Zip Code: 98108      County: King  
Latitude: 47.53240      Longitude: -122.32198      WRIA: 9      Legislative District: 11      Congressional District: 9      TRS: 24N 4E 29

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 4 - Low-Moderate Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Schwarz, Julia      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Independent Metals 2	Upland	Cleanup Started	NW	Schwarz, Julia	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Benzene	S	S				
Dioxins/Furans	S	S	S			
Halogenated Pesticides	S					
Halogenated Solvents	C	C				
Lead	C	C	C			
Mercury	S	S	C			
Metals - Other	S	S	C			
Non-Halogenated Pesticides		S				
Organotins	S	S				
Other Non-Halogenated Organics	S	S	S			
Petroleum-Diesel	C	C	S			
Petroleum-Gasoline	S	S				
Petroleum-Other	C	C	S			
Phenolic Compounds	S	S	S			

# Cleanup Site Details

Cleanup Site ID: 12300

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Polychlorinated biPhenyls (PCB)	S	S	C			
Polycyclic Aromatic Hydrocarbons	S	S	S			

**Key:**

B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected                      R - Remediated    RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/1/2009
Initial Investigation / Federal Preliminary Assessment	Completed		2/14/2014
Early Notice Letter(s)	Completed		2/24/2014
Early Notice Letter(s)	Completed		3/11/2014
Site Hazard Assessment/Federal Site Inspection	Completed	12/15/2014	10/27/2015
Hazardous Sites Listing/NPL	Completed		10/30/2015
LUST - Notification	Completed		8/10/2017
LUST - Report Received	Completed		8/10/2017
Order/Decree/Amendment	In Process	5/19/2022	
Remedial Investigation and/or FS Work Plan	Completed	11/30/2022	5/11/2023
Remedial Investigation and/or Feasibility Study	In Process	5/11/2023	