

Cleanup Site ID: 12408

Cleanup Site Details

Facility/Site ID: 4321 UST ID: 620148 Site Page Site Documents View Map

Cleanup Site ID: 12408

Cleanup Site Name: Morningside Acres

Alternate Names: Morningside Acre Tracts - South, Morningside Acre Tracts South, Morningside Acres, Morningside Acres Tracts South, Murakami

LOCATION

Address: 5021 RAINIER AVE S City: SEATTLE Zip Code: 98118 County: King

Latitude: 47.55642 Longitude: -122.28454 WRIA: 8 Legislative District: 37 Congressional District: 9 TRS: 24N 4E 22

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Wall, Zak Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Morningside Acres South	Upland	Awaiting Cleanup	NW	Wall, Zak	Standard Voluntary Cleanup
Morningside Acres North	Upland	Cleanup Started	NW	Wall, Zak	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
matrument Type	Media	restrictions/requirements	Duto	Number	County	Tax Tarcer

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	С	С					
Halogenated Solvents	С	С			С		
Non-Halogenated Solvents		С					
Petroleum-Diesel	С	С					
Petroleum-Gasoline	С	С					
Petroleum-Other	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		10/23/2013
LUST - Notification	Completed		10/23/2013
LUST - Report Received	Completed		10/23/2013
Initial Investigation / Federal Preliminary Assessment	Completed		10/31/2013

Toxics Cleanup Program Report Generated: 7/1/2025 Page 1 of 2



SHARP Assessment

VCP Technical Assistance

Cleanup Site Details

ECOLOGY State of Washington	Cleanup Site Details		Cleanup Site ID: 12408				
SITE ACTIVITIES							
Activity		Status	Start Date	End Date/ Completion Date			
Early Notice Letter(s)		Completed		2/27/2015			
Site Hazard Assessment		Completed	4/7/2015	8/19/2015			
Hazardous Sites Listing		Completed		8/19/2015			
VCP Receipt of Plan or Report		Completed		6/27/2022			
LUST - Notification		Completed		6/27/2022			
VCP Opinion on Feasibility Study		Completed	6/27/2022	12/12/2022			
VCP Technical Assistance		Completed		1/26/2023			
VCP Receipt of Plan or Report		Completed		4/17/2023			
VCP Opinion on Remedial Investigation		Completed	4/17/2023	5/23/2023			
VCP Technical Assistance		Completed		6/14/2023			
VCP Receipt of Plan or Report		Completed		7/6/2023			
VCP Technical Assistance		Completed		7/10/2023			
VCP Receipt of Plan or Report		Completed		8/8/2023			
VCP Opinion on Property Cleanup Plan		Completed	8/9/2023	12/19/2023			
VCP Receipt of Plan or Report		Completed		11/14/2023			
VCP Technical Assistance		Completed		1/11/2024			

Completed

Completed

4/29/2024

5/3/2024