

Cleanup Site Details

Cleanup Site ID: 12540

Cleanup Site ID: 12540 Facility/Site ID: 77319379 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Grain Handling Facility at Freeman [Glossary](#)

Alternate Names: CENEX HARVEST STATES FREEMAN, Grain Handling Facility at Freeman

LOCATION

Address: 14603 S STATE HWY 27 City: FREEMAN Zip Code: 99036 County: Spokane
Latitude: 47.51996 Longitude: -117.19347 WRIA: 56 Legislative District: 9 Congressional District: 5 TRS: 23N 44E 1

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: Federal - CERCLA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: N/A Brownfield? No
Site Manager: Treccani, Sandra Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Grain Handling Facility at Freeman	Upland	Cleanup Started	EA	Treccani, Sandra	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Pesticides	C	C				
Halogenated Solvents	S	C				
Non-Halogenated Solvents	S	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Federal Site Inspection	Completed		
National Priorities Listing	Completed		
Initial Investigation / Federal Preliminary Assessment	Completed		4/30/2013
Site Hazard Assessment/Federal Site Inspection	Completed		7/31/2014
Early Notice Letter(s)	Completed		2/17/2015
Order/Decree/Amendment	In Process	6/25/2015	
Hazardous Sites Listing/NPL	Completed		9/29/2015
Remedial Investigation and/or FS Work Plan	Completed	12/4/2015	4/7/2016

Cleanup Site Details

Cleanup Site ID: 12540

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	4/8/2016	2/3/2021
Interim Action - Plan	Completed	10/19/2018	3/13/2020
Interim Action - Construction	Completed	3/13/2020	6/1/2021
Interim Action - Performance Monitoring	In Process	6/1/2021	