

Cleanup Site Details

Cleanup Site ID: 12564

Cleanup Site ID: 12564 Facility/Site ID: 24748 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Seattle Temp FS 17 HOT [Glossary](#)

Alternate Names: Seattle Temp FS 17 HOT, UW Surface Lot 1

LOCATION

Address: 4513-4557 11th Ave NE City: Seattle Zip Code: 98105 County: King
Latitude: 47.66233 Longitude: -122.31584 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 8

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 1/29/2009 Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Seattle Temp FS 17 HOT	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		10/29/2008
Initial Investigation / Federal Preliminary Assessment	Completed		1/29/2009
Site Status Changed to NFA	Completed		1/29/2009