DEPARTMENT OF ECOLOGY State of Washington		Cleanup Site Details							Cleanup Site ID: 12736				
Cleanup Site ID: 12736 Facility/Site ID:			5444576	US	UST ID: 100478			Site Pag	e <u>S</u> i	ite Docu	<u>View Map</u>		
Cleanup Site Name: Fro	ontier Corner											<u>Glossary</u>	
Alternate Names: FRONTIER CORNER													
LOCATION													
Address: 10706 HWY 2		City: COULEE CITY Zip Code: 99115						115	County: Grant				
Latitude: 47.63878	19.26290	WRIA: 42 Legislative District: 12 Congression					onal D	<b>I District:</b> 4 <b>TRS:</b> 25N 28E 26					
DETAIL													
Status: No Further Ac	NFA	Received?	Yes	és <b>is PSI</b> s				SI site	site? No				
Statute: MTCA NFA			Date:	8/5/2	8/5/2015 Curren				rent \	/CP?	No Pas	t VCP? No	
Site Rank: N/A	NFA	Reason:	Initia	al Investigation Brown				wnfiel	d?	No			
Site Manager: Eastern F	Resp	onsible Unit:	Easte	ern Active				ive Ins	Institutional Control? No				
CLEANUP UNITS													
Cleanup Unit Name Unit Type			Uni	t Status		Resp Unit	Uni	Unit Manager		Current Process			
Frontier Corner Upland			No Further Action Required			EA	EA Eastern Region			Independent Action			
ACTIVE INSTITUTIONAL CONTROLS													
	Restriction Restrictions/Requir				its Date						ording unty	Tax Parcel	
There are no current Institutional Controls in effect for this site.													
AFFECTED MEDIA & CONTAMINANTS													
							MEDIA						
Contaminant Petroleum-Gasoline				oil	Groundwater		Surface Water		Sedi	ment	Air	Bedrock	
Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below													
SITE ACTIVITIES													
Activity							Status					End Date/ npletion Date	
Petroleum Contaminated Soil Model Remedies							Completed			7/28/2015			
LUST - Notification							Completed			8/5/2015			
Site Status Changed to NFA							Completed			8/5/2015			