

Cleanup Site Details

Cleanup Site ID: 12864

Cleanup Site ID: 12864 Facility/Site ID: 83971759 UST ID: 10904 Site Page Site Documents View Map

Cleanup Site Name: Market Street Spirit Texaco

Alternate Names: MARKET STREET SPIRIT SERVICE, Market Street Spirit Texaco, MARKET STREET TEXACO

LOCATION

Address: 5505 24TH AVE NW City: SEATTLE Zip Code: 98107 County: King

Latitude: 47.66895 Longitude: -122.38800 WRIA: 8 Legislative District: 36 Congressional District: 7 TRS: 25N 3E 11

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-----------------------------|-----------|------------------|--------------|------------------|-----------------|
| Market Street Spirit Texaco | Upland | Awaiting Cleanup | NW | Northwest Region | No Process |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|----------------------|---------------------------|------|---------------------|---------------------|------------|
|-----------------|----------------------|---------------------------|------|---------------------|---------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| | MEDIA | | | | | | |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|--|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock | |
| Benzene | С | С | | | | | |
| Lead | В | В | | | | | |
| Methyl tertiary-butyl ether | | С | | | | | |
| Other Non-Halogenated Organics | С | В | | | | | |
| Petroleum-Diesel | В | В | | | | | |
| Petroleum-Gasoline | С | С | | | | | |
| Petroleum-Other | С | В | | | | | |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|------------------------------|
| LUST - Report Received | Completed | | 7/31/2015 |
| LUST - Notification | Completed | | 8/3/2015 |
| Site Discovery/Release Report Received | Completed | | 8/4/2015 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 8/20/2015 |

Toxics Cleanup Program Report Generated: 8/27/2025 Page 1 of 2



Cleanup Site Details

| SITE ACTIVITIES | | | | |
|------------------------|-----------|------------|------------------------------|--|
| Activity | Status | Start Date | End Date/ Completion Date | |
| Early Notice Letter(s) | Completed | | 10/7/2015 | |

Cleanup Site ID: 12864