

Cleanup Site Details

Cleanup Site ID: 12971

Cleanup Site ID: 12971 **Facility/Site ID:** 16817 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Greenbuild Heating Oil Spill [Glossary](#)
Alternate Names: Greenbuild Heating Oil Spill

LOCATION

Address: 2024 NW 62ND ST **City:** SEATTLE **Zip Code:** 98107 **County:** King
Latitude: 47.67405 **Longitude:** -122.38329 **WRIA:** 8 **Legislative District:** 36 **Congressional District:** 7 **TRS:** 25N 3E 11

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 1/19/2016 **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** Initial Investigation **Brownfield?** No
Site Manager: Musa, Donna **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Greenbuild Heating Oil Spill	Upland	No Further Action Required	NW	Musa, Donna	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/11/2016
Petroleum Contaminated Soil Model Remedies	Completed		1/15/2016
Initial Investigation / Federal Preliminary Assessment	Completed		1/19/2016
Site Status Changed to NFA	Completed		1/19/2016