DEPARTMENT OF					
ECOLOGY					
 State of Washington					

Cleanup Site Details

Cleanup Site ID: 12971

Cleanup Site ID: 12	2971 Facil	ity/Site ID: 168	817 UST ID: N/A			Site Page		e Documents	<u>S View Map</u>		
Cleanup Site Name: Greenbuild Heating Oil Spill Glossary											
Alternate Names: Greenbuild Heating Oil Spill											
LOCATION											
Address: 2024 NW	62ND ST	City: SEATTLE			E	Zip Code: 98107 County: King					
Latitude: 47.67405	Longitude: -1	122.38329 W	RIA: 8	Legislative D	strict:	6 Congressional District: 7 TRS: 25N 3E 11					
DETAIL											
Status: No Furthe	er Action	NFA Re	ceived?	Yes		ls	PSI site?	P No			
Statute: MTCA		NFA Da	te:	1/19/2016		Current VCP? No Past VCP? No					
Site Rank: N/A	ite Rank: N/A NFA Reason: Initial Investigati			tion	on Brownfield? No						
Site Manager: Northwest Region Responsible Unit: Northwest					A	Active Institutional Control? No					
CLEANUP UNITS											
Cleanup Ui	nit Name	Unit Type			Resp Unit	Unit Manage	er	Current Process			
Greenbuild Heating (Dil Spill	Upland N	No Further Action Required		NW	Northwest Rec	jion	Independent Action			
ACTIVE INSTITUTIONAL CONTROLS											
Instrument Type	Restriction Media	Restric	rictions/Requirements				rding nber	Recording County	Tax Parcel		
There are no current Institutional Controls in effect for this site.											
AFFECTED MEDIA & CONTAMINANTS											
MEDIA											
Contaminant			Soi		water	Surface Water	Sedim	ent Ai	r Bedrock		
Petroleum-Diesel			RE	3							
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below											
SITE ACTIVITIES											
Activity						Status	Start D	Date	End Date/ Completion Date		
Site Discovery/Release Report Received					C	Completed			1/11/2016		
Petroleum Contaminated Soil Model Remedies					C	Completed			1/15/2016		
Initial Investigation / Federal Preliminary Assessment					C	Completed			1/19/2016		
Site Status Changed to NFA						Completed 1/19/2016					