

Cleanup Site Details

Cleanup Site ID: 13028

Cleanup Site ID: 13028	Facility/Site ID: 1638	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Perrigo Park Phase 2A					Glossary
Alternate Names: Perrigo Park Phase 2a					

LOCATION

Address: 9011 196th Ave NE	City: Redmond	Zip Code: 98053	County: King
Latitude: 47.68322	Longitude: -122.08109	WRIA: 8	Legislative District: 45
		Congressional District: 1	TRS: 25N 6E 6

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 4/25/2016	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Initial Investigation	Brownfield? No
Site Manager: Musa, Donna	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Perrigo Park Phase 2A	Upland	No Further Action Required	NW	Musa, Donna	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		11/11/2015
Non-LUST Ind Report Received	Completed		11/19/2015
Petroleum Contaminated Soil Model Remedies	Completed		11/19/2015
Non-LUST Ind Report Received	Completed		4/4/2016
Initial Investigation / Federal Preliminary Assessment	Completed		4/5/2016
Site Status Changed to NFA	Completed		4/25/2016