

Cleanup Site Details

Cleanup Site ID: 13028

Cleanup Site ID: 13028 Facility/Site ID: 1638 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Perrigo Park Phase 2A Glossary

Alternate Names: Perrigo Park Phase 2a

LOCATION

Address: 9011 196th Ave NE City: Redmond Zip Code: 98053 County: King

Latitude: 47.68322 Longitude: -122.08109 WRIA: 8 Legislative District: 45 Congressional District: 1 TRS: 25N 6E 6

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 4/25/2016 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Perrigo Park Phase 2A
 Upland
 No Further Action Required
 NW
 Northwest Region
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/11/2015
Non-LUST Ind Report Received	Completed		11/19/2015
Petroleum Contaminated Soil Model Remedies	Completed		11/19/2015
Non-LUST Ind Report Received	Completed		4/4/2016
Initial Investigation / Federal Preliminary Assessment	Completed		4/5/2016
Site Status Changed to NFA	Completed		4/25/2016

Toxics Cleanup Program Report Generated: 5/5/2024 Page 1 of 1