

Cleanup Site Details

Cleanup Site ID: 13054

Cleanup Site ID: 13054 Facility/Site ID: 96127971 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Mt Baker Properties Glossary

Alternate Names: Maddux - MBHA, MBHA 1, Mount Baker Cleaners, Mt Baker Properties, Phillips 66 070644

LOCATION

Address: 2864 S McClellan St City: Seattle Zip Code: 98144 County: King

Latitude: 47.57861 Longitude: -122.29538 WRIA: 8 Legislative District: 37 Congressional District: 9 TRS: 24N 4E 9

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? Yes

Site Manager: Matthews, Sandra Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Mt Baker Properties
 Upland
 Cleanup Started
 NW
 Matthews, Sandra
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents		С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/6/2009
Order/Decree/Amendment	In Process	10/28/2016	
Remedial Investigation and/or FS Work Plan	Completed	12/8/2016	10/27/2017
Order/Decree/Amendment	In Process	8/30/2017	
Remedial Investigation and/or Feasibility Study	Completed	10/27/2017	12/31/2019
Cleanup Action Plan	Completed	12/31/2019	1/6/2020

Toxics Cleanup Program Report Generated: 7/31/2025 Page 1 of 1