DEPARTMENT OF ECOLOGY
State of Washington

Cleanup Site Details

Cleanup Site ID: 13055

Cleanup Site ID: 13055 **Facility/Site ID:** 7890 **UST ID:** N/A Site Page | Site Documents | View Map

Cleanup Site Name: Star Lake Elementary Glossary

Alternate Names: Star Lake Elementary, Star Lake Elementary Heating Oil Tank

LOCATION

Address: 4014 S 270TH ST **City:** KENT **Zip Code:** 98032 **County:** King

Latitude: 47.36031 **Longitude:** -122.28286 **WRIA:** 9 **Legislative District:** 33 **Congressional District:** 9 **TRS:** 22N 4E 27

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** Yes **Past VCP?** Yes

Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No

Site Manager: Barber, Eva **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Star Lake Elementary	Upland	Cleanup Started	SW	Barber, Eva	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Arsenic	C					
Lead	B					

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		5/13/2020
VCP Receipt of Plan or Report	Completed		5/13/2020
VCP Receipt of Plan or Report	Completed		5/13/2020
VCP Opinion on Remedial Investigation Work Plan	Completed	5/19/2020	7/6/2020