

Cleanup Site Details

Cleanup Site ID: 13066

Cleanup Site ID: 13066 Facility/Site ID: 43787415 UST ID: 5093 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Southcenter Chevron Hoists [Glossary](#)

Alternate Names: CHEVRON 91557, Chevron USA Inc SS 91557, SOUTHCENTER CHEVRON, Southcenter Chevron Hoists, Strander Chevron

LOCATION

Address: 220 STRANDER BLVD City: TUKWILA Zip Code: 98188 County: King
Latitude: 47.45566 Longitude: -122.26090 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS:

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 6/21/2016 Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Southcenter Chevron Hoists	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/13/2015
Non-LUST Ind Report Received	Completed		1/4/2016
Initial Investigation / Federal Preliminary Assessment	Completed		2/29/2016
Petroleum Contaminated Soil Model Remedies	Completed		2/29/2016
Site Status Changed to NFA	Completed		6/21/2016