

Cleanup Site Details

Cleanup Site ID: 13146

Cleanup Site ID: 13146 Facility/Site ID: 55168441 UST ID: 3425 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Pettit Oil Company Tumwater Truck Route [Glossary](#)

Alternate Names: PETTIT OIL CO 2ND & TUMWATER, PETTIT OIL CO 7TH & TUMWATER, PETTIT OIL COMPANY, Pettit Oil Company Tumwater Truck Route, PETTIT OIL COMPANY TUMWATER TRUCK RTE

LOCATION

Address: 220 TUMWATER TRUCK RTE City: PORT ANGELES Zip Code: 98362 County: Clallam

Latitude: 48.12195 Longitude: -123.44577 WRIA: 18 Legislative District: 24 Congressional District: 6 TRS:

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: N/A NFA Reason: N/A Brownfield? No
 Site Manager: Praisewater, Thomas Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Former Pettit Oil Kardlock	Upland	Cleanup Started	SW	Groven, Connie	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	B	B				
Other Non-Halogenated Organics	B	B				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	B	S				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		3/13/2000
LUST - Report Received	Completed		3/13/2000
Site Discovery/Release Report Received	Completed		6/3/2016
Initial Investigation / Federal Preliminary Assessment	Completed		10/12/2016
Early Notice Letter(s)	Completed		10/28/2016