

Cleanup Site Details

Cleanup Site ID: 13238

Cleanup Site ID: 13238	Facility/Site ID: 5619	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Vander Hoek Property					Glossary	
Alternate Names: Vander Hoek Property						
LOCATION						
Address: 22 103RD AVE NE		City: BELLEVUE	Zip Code: 98004	County: King		
Latitude: 47.61098	Longitude: -122.20251	WRIA: 8	Legislative District: 41	Congressional District: 9	TRS: 25N 5E 32	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 5/22/2017	Current VCP? No		Past VCP? No		
Site Rank: N/A	NFA Reason: Initial Investigation	Brownfield? No				
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control?		No		
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Vander Hoek Property	Upland	No Further Action Required	NW	Warfel, Michael	Independent Action	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					
Petroleum-Other	B					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed			9/28/2016		
Non-LUST Ind Report Received	Completed			11/17/2016		
Petroleum Contaminated Soil Model Remedies	Completed			11/17/2016		
Initial Investigation / Federal Preliminary Assessment	Completed			5/3/2017		
Site Status Changed to NFA	Completed			5/22/2017		