State of Washington	(Cleanup	p Site I	Deta	ails		Clean	up Site	ə ID: 13313	
Cleanup Site ID: 13313 Facili	ity/Site ID: 9	4994182	UST ID: 11	724	<u>Site I</u>	Page S	ite Docume	ents	<u>View Map</u>	
Cleanup Site Name: Swedish Edmon	ds Hospital A	ST Spill							<u>Glossary</u>	
Alternate Names: STEVENS HEALTH	HCARE, Steve	ens Memorial Ho	ospital, Swedis	h Edmoi	nds, Swedish E	dmonds H	lospital AST	Spill		
LOCATION										
Address: 21601 76TH AVE W			City: EDMO	NDS	Zip Code:	98026	County:	Snoho	mish	
Latitude: 47.80329 Longitude: -1	122.33418	WRIA: 8	Legislative D	istrict:	32 Congre	ssional E	District: 7	TRS:	27N 4E 29	
DETAIL										
Status: No Further Action NFA Received?			Yes Is PSI s				e? No			
statute: MTCA NFA Date:			7/24/2017 Curren				VCP? No	Past	VCP? No	
Site Rank: N/A	NFA F	Reason:	Initial Investiga	ition		Brownfie	ld? No			
Site Manager: Northwest Region	Resp	onsible Unit:	Northwest			Active In	stitutional	Control	? No	
CLEANUP UNITS										
Cleanup Unit Name	Unit Type	Unit St	Status Resp Unit Un		Unit Mana	ager Curre		rent Pro	ent Process	
Swedish Edmonds Hospital AST Spill	Upland	No Further Act	ion Required	NW	Northwest R	Region Independent A		Action		
ACTIVE INSTITUTIONAL CONTROLS										
Instrument Type Restriction Media	Restrictions/Requirements			Date Recording Number						
AFFECTED MEDIA & CONTAMINANT	-S				M					
	'S	Soil	Ground	lwater		EDIA	iment	Air	Bedrock	
AFFECTED MEDIA & CONTAMINANT Contaminant Benzene	-S	Soil B	Ground	lwater	Mi Surface Wate		iment	Air	Bedrock	
Contaminant Benzene	S		Ground	lwater			iment	Air	Bedrock	
Contaminant Benzene	-S	B	Ground	lwater			iment	Air	Bedrock	
Contaminant Benzene Non-Halogenated Solvents	"S	B	Ground	lwater			iment	Air	Bedrock	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Cor		B RB RB	Ground RA - Ren RB - Ren	nediated	Surface Wate		iment	Air	Bedrock	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Cor	nfirmed Above	B RB RB RB	RA - Ren	nediated	Surface Wate		iment	Air	Bedrock	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Con S - Suspected R - Ren SITE ACTIVITIES	nfirmed Above	B RB RB RB	RA - Ren	nediated	Surface Wate	er Sedi	iment iment interval interva		Bedrock	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Con S - Suspected R - Ren SITE ACTIVITIES Activity	nfirmed Above	B RB RB RB	RA - Ren	nediated	Surface Wate	er Sedi		E Com	nd Date/	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Con S - Suspected R - Ren SITE ACTIVITIES Activity Site Discovery/Release Report Receive	nfirmed Above	B RB RB RB	RA - Ren		Surface Wate -Above -Below Status	er Sedi		E Com	nd Date/ pletion Date	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Con S - Suspected R - Ren SITE ACTIVITIES Activity Site Discovery/Release Report Received Non-LUST Ind Report Received	nfirmed Above nediated	B RB RB RB	RA - Ren	nediated nediated	Surface Wate	er Sedi		E Com 12 5	nd Date/ pletion Date 2/21/2016	
Contaminant Benzene Non-Halogenated Solvents Petroleum-Diesel Petroleum-Other Key: B - Below Cleanup Level C - Cor S - Suspected R - Ren	nfirmed Above nediated	e Cleanup Level	RA - Ren	nediated nediated contraction	Surface Wate -Above -Below Status Completed Completed	er Sedi		E Com 12 5 5	nd Date/ pletion Date 2/21/2016 /25/2017	