

Cleanup Site Details

Cleanup Site ID: 1339

Cleanup Site ID: 1339	Facility/Site ID: 12448	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Beth Lake Prospect					Glossary	
Alternate Names: Beth Lake Prospect						
LOCATION						
Address:		City: Oroville	Zip Code: 98844	County: Okanogan		
Latitude: 48.86191	Longitude: -118.99330	WRIA: 60	Legislative District: 7	Congressional District: 4	TRS: 39N 30E 23	
DETAIL						
Status: Cleanup Started	NFA Received? No	Is PSI site? No				
Statute: MTCA	NFA Date: N/A	Current VCP? No	Past VCP? No			
Site Rank: N/A	NFA Reason: N/A	Brownfield? No				
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control?	No			
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Beth Lake Prospect	Upland	Cleanup Started	CE	Central Region	Independent Action	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Discovery/Release Report Received	Completed		4/12/2010			