

Cleanup Site Details

Cleanup Site ID: 1361

Cleanup Site ID: 1361 Facility/Site ID: 2231 UST ID: 100187 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Northwest Plating [Glossary](#)

Alternate Names: NORTHWEST PLATING, NORTHWEST PLATING COMPANY, Washington Industries

LOCATION

Address: 825 S DAKOTA ST City: SEATTLE Zip Code: 98108 County: King
Latitude: 47.56696 Longitude: -122.32223 WRIA: 9 Legislative District: 11 Congressional District: 7 TRS: 24N 4E 17

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes
Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
Site Manager: Song, Jing Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Northwest Plating	Upland	Cleanup Started	NW	Song, Jing	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				
Metals Priority Pollutants	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Non-LUST Ind Report Received	Completed		6/9/2011
Non-LUST Ind Report Received	Completed		6/9/2011
Non-LUST Ind Report Received	Completed		6/6/2013
Initial Investigation / Federal Preliminary Assessment	Completed		8/12/2013
VCP Opinion on Site Cleanup Plan	Completed	8/12/2013	11/26/2013
VCP Receipt of Plan or Report	Completed		11/27/2013
VCP Receipt of Plan or Report	Completed		7/13/2016
VCP Opinion on Remedial Investigation	Completed	7/13/2016	6/18/2018

Cleanup Site Details

Cleanup Site ID: 1361

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		1/25/2017
VCP Receipt of Plan or Report	Completed		5/19/2017
VCP Receipt of Plan or Report	Completed		4/17/2018
VCP Receipt of Plan or Report	Completed		4/24/2018
VCP Receipt of Plan or Report	Completed		6/7/2018
Site Hazard Assessment	Completed	10/12/2018	8/14/2019
VCP Receipt of Plan or Report	Completed		7/22/2019
Hazardous Sites Listing	Completed		8/16/2019
VCP Receipt of Plan or Report	Completed		12/30/2019
VCP Opinion on Site Cleanup Plan	Completed	12/30/2019	8/26/2020
VCP Status Request	Completed	9/21/2021	1/21/2022
VCP Receipt of Plan or Report	Completed		9/23/2021
VCP Receipt of Plan or Report	Completed		9/23/2021
VCP Receipt of Plan or Report	Completed		12/29/2021
VCP Opinion on Site Cleanup	Canceled	1/21/2022	1/1/1900
VCP Receipt of Plan or Report	Completed		8/30/2022
VCP Opinion on Property Cleanup	Completed	7/28/2023	12/29/2023
VCP Receipt of Plan or Report	Completed		2/23/2024