

Cleanup Site Details

Cleanup Site ID: 14339

Cleanup Site ID: 14339 Facility/Site ID: 66571524 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Lowes Diesel Surface Spill [Glossary](#)

Alternate Names: EAGLE HARDWARE & GARDEN 405, Lowes Diesel Surface Spill, Lowes HIW 061

LOCATION

Address: 3300 169TH PL NE City: ARLINGTON Zip Code: 98223 County: Snohomish
Latitude: 48.14937 Longitude: -122.18632 WRIA: 7 Legislative District: 39 Congressional District: 2 TRS: 31N 5E 29

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 6/19/2017 Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Lowes Diesel Surface Spill	Upland	No Further Action Required	NW	Musa, Donna	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					
Petroleum-Other	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		2/22/2016
Petroleum Contaminated Soil Model Remedies	Completed		3/28/2017
Initial Investigation / Federal Preliminary Assessment	Completed		3/28/2017
Site Status Changed to NFA	Completed		6/19/2017