DEPARTMENT	OF
ECOLOC	Y
 State of Washing	ton

Cleanup Site Details

Cleanup Site ID: 1434

Cleanup Site ID: 1	434 Fa	cility/Site ID:	7681	UST ID: N/A	۱		Site Pag	<u>e Sit</u>	e Documer	<u>nts</u>	View Map
Cleanup Site Name	e: MJB South Hy	ydro Fill									<u>Glossary</u>
Alternate Names:	MJB SOUTH HY	DRO FILL									
LOCATION											
Address: TAVE 25	5TH & 30TH ST			City: ANACC	RTES	Zip(Code: 98	221	County:	Skagit	
Latitude: 48.50013	B Longitude:	-122.60535	WRIA: 3	Legislative D	istrict:	40 C	ongressi	onal Dis	strict: 2	TRS:	35N 2E 19
DETAIL											
Status: Cleanup	Started	NFA	Received?	No			ls F	PSI site?	? Yes		
Statute: MTCA		NFA	Date:	N/A			Cu	rrent V	CP? No	Past	VCP? No
Site Rank: 2 - Mode	erate-High Risk	NFA	Reason:	N/A			Bro	ownfield	I? No		
Site Manager: Hor	ne, David	Resp	onsible Unit:	Headquarters			Act	ive Inst	itutional C	ontrol	? Yes
CLEANUP UNITS											
Cleanup U	nit Name	Unit Type	Unit	Status	Resp Unit	Unit	t Manager		Curr	ent Pro	ocess
MJB South Hydro Fi	II	Upland	No Further A	ction Required	HQ	Hor	ne, David		No	o Proce	ess
South Hydro Fill Sec	liment	Sediment	Awaitinę	g Cleanup	HQ	Hea	adquarters		No	o Proce	ess
ACTIVE INSTITUTION	ONAL CONTRO	LS									
Instrument Type	Restriction Media	Rest	rictions/Requi	irements		Date	Recor Num		Recordin County		Tax Parcel
Environmental Covenant	Groundwater	Restrict Land I	Jse		10/2	3/2024	2024102	230059	Skagit	P3 P3 P3 P3	2972; P32974; 2975; P32976; 2977; P32979; 2981; P78002; 2806; P131158
Institutional Control of please see the Envi				ocuments' link at	the top c	of the pa	ge. For mo	ore detai	ls on Institu	tional	Controls,
AFFECTED MEDIA	& CONTAMINA	NTS									
							MEDI				
Contaminant			So			Surfac	e Water	Sedim	nent A	Air	Bedrock
Arsenic				R/	`						
Benzene				В				0			
Dioxins/Furans			B					S			
Halogenated Solven	IS		R								
Lead				R/	`						
Metals Priority Pollut			RI								
Non-Halogenated So			В								
Other Non-Halogena	ated Organics			В							
Petroleum-Diesel			В								
Petroleum-Gasoline			В								
Petroleum-Other			В					S			
Polychlorinated biPh	enyls (PCB)		В					S			
Toxics Cleanu	p Program		Repo	ort Generate	d: 8/23	/2025				Page	e 1 of 2



Cleanup Site Details

Cleanup Site ID: 1434

Contaminant		Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Polycyclic Aromatic Hydrocarbons		В	В		S		
Key: B - Below Cleanup Level S - Suspected	C - Confirmed Above Clea R - Remediated	nup Level	RA - Remediate RB - Remediate		11		1
SITE ACTIVITIES							
Activity			Status	Start Date		End Date/ Completion Date	
Site Discovery/Release Report Received				Completed	4	4/28/1992	
Initial Investigation / Federal P	reliminary Assessment			Completed		9	9/9/1992
Early Notice Letter(s)				Completed		2	/10/1995
Site Hazard Assessment				Completed	11/3/2003	1	2/5/2004
Hazardous Sites Listing				Completed		1	2/5/2004
SHARP Assessment				Completed		1	1/13/2024
Periodic Review				Completed	1/1/2025	4	4/2/2025