

Cleanup Site Details

Cleanup Site ID: 1434

Cleanup Site ID: 1434
Facility/Site ID: 7681
UST ID: N/A
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: MJB South Hydro Fill
[Glossary](#)
Alternate Names: MJB SOUTH HYDRO FILL

LOCATION

Address: T AVE 25TH & 30TH ST
City: ANACORTES
Zip Code: 98221
County: Skagit
Latitude: 48.50013
Longitude: -122.60535
WRIA: 3
Legislative District: 40
Congressional District: 2
TRS: 35N 2E 19

DETAIL

Status: Awaiting Cleanup
NFA Received? No
Is PSI site? Yes
Statute: MTCA
NFA Date: N/A
Current VCP? No
Past VCP? No
Site Rank: 2 - Moderate-High Risk
NFA Reason: N/A
Brownfield? No
Site Manager: Horne, David
Responsible Unit: Headquarters
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
MJB South Hydro Fill	Upland	No Further Action Required	HQ	Horne, David	No Process
South Hydro Fill Sediment	Sediment	Awaiting Cleanup	HQ	Headquarters	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Dioxins/Furans	RB			S		
Metals Priority Pollutants	RB					
Non-Halogenated Solvents	RB					
Petroleum Products-Unspecified	RB					
Petroleum-Other				S		
Phenolic Compounds	RB					
Polychlorinated biPhenyls (PCB)				S		
Polycyclic Aromatic Hydrocarbons	RB			S		

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		9/9/1992

Cleanup Site Details

Cleanup Site ID: 1434

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		2/10/1995
Site Hazard Assessment/Federal Site Inspection	Completed	11/3/2003	12/5/2004
Hazardous Sites Listing/NPL	Completed		12/5/2004