

Cleanup Site ID: 14341

Cleanup Site Details

Facility/Site ID: 10202 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 14341

Cleanup Site Name: Olmsted Transportation Spill

Alternate Names: Olmsted Transportation Spill

LOCATION

Address: R-O-W 27121 SR 9 NE City: ARLINGTON Zip Code: 98223 County: Snohomish

Latitude: 48.24239 Longitude: -122.16031 WRIA: 5 Legislative District: 10 Congressional District: 1 TRS: 32N 5E 22

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 7/24/2017 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name Unit Type Unit Status Resp Unit Unit Manager Current Process

Olmsted Transportation Spill Upland No Further Action Required NW Northwest Region Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA				
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/27/2016
Petroleum Contaminated Soil Model Remedies	Completed		1/27/2016
Non-LUST Ind Report Received	Completed		1/27/2016
Initial Investigation / Federal Preliminary Assessment	Completed		7/17/2017
Site Status Changed to NFA	Completed		7/24/2017

Toxics Cleanup Program Report Generated: 11/4/2025 Page 1 of 1