

Cleanup Site Details

Cleanup Site ID: 14472

Cleanup Site ID: 14472 Facility/Site ID: 91995 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Nash Holland 1001 Minor [Glossary](#)

Alternate Names: Nash Holland 1001 Minor

LOCATION

Address: 1001 MINOR AVE & 1114 Madison St City: SEATTLE Zip Code: 98104 County: King
 Latitude: 47.60989 Longitude: -122.32456 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 32

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
 Statute: MTCA NFA Date: 2/13/2018 Current VCP? No Past VCP? No
 Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No
 Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Nash Holland 1001 Minor	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	B					
Other Non-Halogenated Organics	B					
Petroleum-Diesel	B					
Petroleum-Gasoline	B					
Petroleum-Other	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		2/8/2018
Petroleum Contaminated Soil Model Remedies	Completed		2/8/2018
Non-LUST Ind Report Received	Completed		2/13/2018
Initial Investigation / Federal Preliminary Assessment	Completed		2/13/2018
Site Status Changed to NFA	Completed		2/13/2018