

Cleanup Site Details

Cleanup Site ID: 14770

Cleanup Site ID: 14770 **Facility/Site ID:** 60939 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Blakely Harbor Park [Glossary](#)
Alternate Names: Blakely Harbor Park

LOCATION

Address: Blakely Ave & 3-T Rd **City:** Bainbridge Island **Zip Code:** 98110 **County:** Kitsap
Latitude: 47.59640 **Longitude:** -122.51498 **WRIA:** 15 **Legislative District:** 23 **Congressional District:** 6 **TRS:**

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: McDermott, Rachel **Responsible Unit:** Headquarters **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-----------------------------|-----------|-----------------|-----------|-------------------|---------------------------------|
| Port Blakely Parks Upland | Upland | Cleanup Started | HQ | McDermott, Rachel | Ecology-supervised or conducted |
| Port Blakely Parks Sediment | Sediment | Cleanup Started | HQ | McDermott, Rachel | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|--|-------------------|---------------------------|------|------------------|------------------|------------|
| There are no current Institutional Controls in effect for this site. | | | | | | |

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|--------------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Conventional Contaminants, Inorganic | S | S | | S | | |
| Conventional Contaminants, Organic | | | | S | | |
| Dioxins/Furans | S | S | | S | | |
| Lead | S | S | | C | | |
| Metals - Other | S | S | | C | | |
| Other Deleterious Substances | | | | C | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed | | 9/21/2018 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 11/29/2018 |
| Early Notice Letter(s) | Completed | | 12/4/2018 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 2/15/2019 | 8/14/2020 |

Cleanup Site Details

Cleanup Site ID: 14770

| SITE ACTIVITIES | | | |
|---|------------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Hazardous Sites Listing/NPL | Completed | | 8/17/2020 |
| Remedial Investigation and/or FS Work Plan | Completed | 4/29/2022 | 4/1/2023 |
| Remedial Investigation and/or Feasibility Study | In Process | 5/16/2024 | |