

Cleanup Site Details

Cleanup Site ID: 14770

Cleanup Site ID: 14770 **Facility/Site ID:** 60939 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Blakely Harbor Park [Glossary](#)
Alternate Names: Blakely Harbor Park

LOCATION

Address: Blakely Ave & 3-T Rd **City:** Bainbridge Island **Zip Code:** 98110 **County:** Kitsap
Latitude: 47.59640 **Longitude:** -122.51498 **WRIA:** 15 **Legislative District:** 23 **Congressional District:** 6 **TRS:**

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: McDermott, Rachel **Responsible Unit:** Headquarters **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port Blakely Parks Upland	Upland	Cleanup Started	HQ	McDermott, Rachel	Ecology-supervised or conducted
Port Blakely Parks Sediment	Sediment	Cleanup Started	HQ	McDermott, Rachel	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS
MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	S	S		S		
Conventional Contaminants, Organic				S		
Dioxins/Furans	S	S		S		
Lead	S	S		C		
Metals - Other	S	S		C		
Other Deleterious Substances				C		

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/21/2018
Initial Investigation / Federal Preliminary Assessment	Completed		11/29/2018
Early Notice Letter(s)	Completed		12/4/2018
Site Hazard Assessment/Federal Site Inspection	Completed	2/15/2019	8/14/2020

Cleanup Site Details

Cleanup Site ID: 14770

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		8/17/2020
Remedial Investigation and/or FS Work Plan	Completed	4/29/2022	4/1/2023
Remedial Investigation and/or Feasibility Study	In Process	5/16/2024	