

Cleanup Site ID: 14787

Cleanup Site Details

Facility/Site ID: 48336 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 14787

Cleanup Site Name: Stewart House Glossary

Alternate Names: Stewart House

LOCATION

Address: 1733 BELMONT AVE City: SEATTLE Zip Code: 98122 County: King

Latitude: 47.61734 Longitude: -122.32490 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 32

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Wall, Zak Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Stewart House
 Upland
 Awaiting Cleanup
 NW
 Wall, Zak
 No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/18/2017
Initial Investigation / Federal Preliminary Assessment	Completed		9/24/2018
Early Notice Letter(s)	Completed		10/31/2018

Toxics Cleanup Program Report Generated: 4/13/2025 Page 1 of 1